PALVATE - COMPTHENTIAL

DISTRIBUTION SANTA FE FILE			
SANTA FE FILE	} I		Form C-103
FILE			Supersedes Old
···	N	IEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-85
11666			· U. C. C.
U.S.G.S.		APR 24 11 40	5a. Indicate Type of Lease
LAND OFFICE		រ ប៉ុក្	State Fee 🛣
OPERATOR			5. State Oil & Gas Lease No.
(DO NOT USE THIS FORM	SUNDRY NOTICES	S AND REPORTS ON WELLS LL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVE T -'' (FORM C-101) FOR SUCH PROPOSALS.)	
USE "A	PPLICATION FOR PERMIT	(FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL	OTHER-	Stratigraphic Test	7. Unit Agreement Name
2. Name of Operator			8. Farm or Lease Name
	11 oil Compan	У	Shell Strat
3. Address of Operator	O. Box 1509.	Midland, Texas 79701	9. Well No. 2-69
4. Location of Well		77702	10. Field and Pool, or Wildcat
			Wildow
		ET FROM THELINE AND	_ FEET FROM
THELINE	5 SECTION	2-N 29-B	NMPM.
			— "MEM. (())
	15.	, Elevation (Show whether DF, RT, GR, etc.)	12. County
	7////////		Roosevelt
16. CI	heck Appropriate	Box To Indicate Nature of Notice, Rep	ort or Other Data
	OF INTENTION		ISEQUENT REPORT OF:
			SEQUENT REPORT OF.
PERFORM REMEDIAL WORK		PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	<u></u>
PULL OR ALTER CASING		CHANGE PLANS CASING TEST AND CEMENT J	
TOTAL SILVAL SIL			GB
OTHER		OTHER	
17. Describe Proposed or Compl work) SEE RULE 1103.	eted Operations (Clea	urly state all pertinent details, and give pertinent date	s, including estimated date of starting any propose
warm, 322 11322 11331		March 7, 1969	
		Ţ.	
Ran drill	pipe open-end	ded and spotted following plugs	of Class C Neat cement.
	2348 - 2548 '	50 sacks	
	L766 '-1 866'	25 sacks	
1		25 sacks	
1	712'-812'		
	712'-812' 309'-409'	25 sacks	
		1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
	309*-409*	25 sacks	
	309'-409' Surface	25 sacks	
	309'-409' Surface	25 sacks 10 sacks	
	309'-409' Surface	25 sacks 10 sacks	
	309'-409' Surface	25 sacks 10 sacks	
	309'-409' Surface	25 sacks 10 sacks	
	309'-409' Surface	25 sacks 10 sacks	
	309'-409' Surface	25 sacks 10 sacks	
	309'-409' Surface	25 sacks 10 sacks	
	309'-409' Surface	25 sacks 10 sacks	
Plugged ar	309*-409* Surface ad abandoned P	25 sacks 10 sacks	
Plugged ar	309*-409* Surface ad abandoned P	25 sacks 10 sacks March 7, 1969.	
Plugged ar	309*-409* Surface ad abandoned P	25 sacks 10 sacks March 7, 1969.	Engineer 4-22-69
Plugged ar	309*-409* Surface ad abandoned 2	25 sacks 10 sacks March 7, 1969.	Engineer DATE 4-22-69
Plugged ar	309*-409* Surface ad abandoned 2	25 sacks 10 sacks March 7, 1969.	
Plugged ar	309*-409* Surface ad abandoned 2	25 sacks 10 sacks March 7, 1969.	Engineer DATE 4-22-69
Plugged and 18. I hereby certify that the information of the signed and the information of the signed and the information of the signed and t	309*-409* Surface ad abandoned 2	25 sacks 10 sacks March 7, 1969. and complete to the best of my knowledge and belief. TITLE Staff Petrophysical	