

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

JUN 29 2 20 PM '67

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name	
2. Name of Operator Sunray DX Oil Company		8. Farm or Lease Name C. W. Radcliff	
3. Address of Operator P. O. Box 1416, Roswell, New Mexico		9. Well No. 1	
4. Location of Well UNIT LETTER: P, 860 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 6S RANGE 35E NMPM.		10. Field and Pool, or Wildcat Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) 4225 DF		12. County Roosevelt	

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Drilled 12 1/4" hole to 345'. Ran 8 5/8" OD, 20#, J-55 csg to 341', and cemented with 200 sxs reg 2% CaCl. Circulated 20 sxs to surface. WOC 18 hrs. Tested csg to 1000# for 30 min. Held OK.
- Installed BOP and drilled 7 7/8" hole to 4625'. Cut two cores (1st 4000'-4049', 2nd 4100'-4159'). Ran open hole logs.
- Prep to P&A. (Verbal approval by Joe Ramey 6-27-67).
- Will lay cement plugs as follows: 25 sxs @ 4625' up, 25 sxs @ 4050' up, 25 sxs @ 3238' up, 25 sxs @ 2050' up, 25 sxs @ 341' up (in and out of base of surface pipe), and 10 sx plug at surface.
- Install dry hole marker and clear location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Hastings TITLE District Engineer DATE June 28, 1967

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: