

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>		7. Unit Agreement Name
2. Name of Operator <b>Sunray DX Oil Company</b>		8. Farm or Lease Name <b>J. G. Capps</b>
3. Address of Operator <b>P. O. Box 1416 - Roswell, New Mexico</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>E</b> , <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>8</b> TOWNSHIP <b>3-S</b> RANGE <b>35-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4096.6 G.L.</b>		12. County <b>Roosevelt</b>

16.

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. TD 4300'. No productive zones present. Prep to P&A.

2. Will lay cmt. plugs as follows:

25 sxs 4220' - 4300' (Cover top of Glorietta @ 4245)  
25 sxs 2835' - 2915' (Cover top of San Andres @ 2874)  
25 sxs 1775' - 1855' (Cover top of Rustler @ 1814)  
25 sxs 366' - 446' (In & out of 8-5/8" csg. @ 406')  
10 sxs Surface

3. Install Dry Hole Marker

4. Clear location, fill and level pits, and ready location for inspection.

**NOTE: VERBAL APPROVAL OBTAINED 3-7-68.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ralph L. Maness TITLE Acting District Engineer DATE 3-7-68

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: