

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
Western States Producing Company
3. ADDRESS OF OPERATOR
900 Building of the Southwest Midland, Texas 79701
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 1980' FNL & 1980' FWL

14. PERMIT NO. ----- 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4447' GL

5. LEASE DESIGNATION AND SERIAL NO.
NM - 0533777-C
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal "24"
9. WELL NO.
2
10. FIELD AND POOL, OR WIRELIFT
Chaveroo
11. SEC., T., R., OR BLK. AND SURVEY OR AREA
Sec. 24, T-7-S, R-32-E
12. COUNTY OR PARISH
Roosevelt 13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pump 50 sack plug down 4 1/2" casing and displace to 4000'.
2. Free point casing and shoot off at approximately 3700'.
3. Spot 50 sack plug from 3700' to 3500'.
4. Spot 50 sack plug from 1900' to 1767'.
5. Spot 10 sack plug at surface, remove casing head and set mark.

This well is to be abandoned due to production of 100% water from the San Andres producing zone.

18. I hereby certify that the foregoing is true and correct

SIGNED John McCammon

TITLE

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Office Manager
APPROVED

FEB 13 1969

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

DATE 2/11/69

DATE

DATE

DATE

DATE