

UNITED STATES  
DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPlicate\*  
(Other instructions on re-  
verse side)

Form approved  
Budget Bureau No. 12-11404

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

|  |  |
|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>   | 5. LEASE DESIGNATION AND SERIAL NO.<br>NM-034546-B                         |
| 2. NAME OF OPERATOR<br>Southwestern Natural Gas, Inc.  | 6. IF INDIAN, ALLOTTEE OR TRUST NAME<br>---                                |
| 3. ADDRESS OF OPERATOR<br>900 Building of the Southwest Midland, Texas 79701   | 7. UNIT AGREEMENT NAME<br>---  |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>1980' FNL and FEL | 8. FARM OR LEASE NAME<br>Federal "24"                                      |
| 14. PERMIT NO.<br>--   | 9. WELL NO.<br>1   |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br>4459' DF   | 10. FIELD AND POOL, OR WELL AT<br>Chaveroo                                 |
|  | 11. SEC., T., R., M., OR B.E. AND SURVEY OR AREA<br>Sec. 24, T-7-S, R-32-E |
|  | 12. COUNTY OR PARISH 13. STATE<br>Roosevelt New Mexico                     |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Spotted 50 sacks Class "H" cement plug to 4,000'.
2. Cut off casing at approximately 3300' and spotted 50 sacks plug back to 3,000'.
3. Spotted 50 sacks plug from 1880' to 1770'.
4. Spotted 10 sacks plug at surface and set marker.

Date well site will be ready for inspection 4-26-69.

18. I hereby certify that the foregoing is true and correct

SIGNED Don L. Bennett TITLE Operations Manager

DATE 4-11-69

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

\*See Instructions on Reverse Side

