

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions  
verse side)

Form approved  
Budget Bureau No. 42-R1424.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL  GAS WELL  OTHER  Dry

2. NAME OF OPERATOR  
Shell Oil Company

3. ADDRESS OF OPERATOR  
P. O. Box 1509, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)  
At surface 1980' FNL & 660' FEL, Section 23, T-7-S,  
R-32-E. NMPM, Roosevelt County, New Mexico

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
4660 DF

5. LEASE DESIGNATION AND SERIAL NO.  
NM 0533777B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Shell Brukenfeld Federal

9. WELL NO.  
1

10. FIELD AND POOL, OR WILDCAT  
Chaveroo (San Andres)

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA  
Sec. 23, T-7-S, R-32-E,  
NMPM

12. COUNTY OR PARISH  
Roosevelt

13. STATE  
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTERFERENCE TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

3-4-73 to 3-6-74

1. Set CIBP in 4 1/2" casing at 3646'. Set 60' cement plug on top of BP from 3646' up to 3586'.
2. Cut 4 1/2" casing at 1600' and pulled. Circulated hole with 9# mud laden fluid.
3. Set 25 sx Class H cement plug 1477-1595'.
4. Set 35 sx Class H cement plug 270-435'.
5. Set cement plug from surface to 30' and installed steel marker. Well Plugged and Abandoned 3-6-74.

Location cleared and ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED N. W. Harrison TITLE Staff Production Engineer DATE 3-20-74

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

**APPROVED**  
APR 19 1974  
ARTHUR R. BROWN  
DISTRICT ENGINEER

\*See Instructions on Reverse Side