

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Williams Ranch
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Roosevelt

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry Hole
2. Name of Operator Ernest A. Hanson & Wilbur L. Shackelford
3. Address of Operator P. O. Box 1515, Roswell, New Mexico
4. Location of Well UNIT LETTER B , 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 3-5 RANGE 36-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3983' KB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Permission to plug and abandon the captioned well is hereby requested. It is proposed to set cement plugs in heavy mud at the following depths:

25 sacks @ Top of San Andres Formation.
25 sacks @ Top of Salt Formation.
25 sacks in-and-out of 8-5/8" surface casing.
10 sacks at the surface.

The location will then be cleaned up and a regulation dry hole marker erected.

Verbal permission to plug and abandon the captioned well in this manner was granted via telephone by Mr. Joe Ramey on Sept. 27, 1968.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Mary P. Schaefer</i></u>	TITLE <u>Exploration Manager</u>	DATE <u>Sept. 30, 1968</u>
APPROVED BY <u><i>Joe Ramey</i></u>	TITLE _____	DATE _____
REMARKS OF APPROVAL, IF ANY:		