

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

HOBBS OFFICE O. C. C.  
MAY 27 10 30 AM '69

14. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>Dry hole</b>	7. Unit Agreement Name
2. Name of Operator <b>Hanson Oil Company &amp; Wilbur L. Shackelford</b>	8. Farm or Lease Name <b>Blackwater Draw</b>
3. Address of Operator <b>P. O. Box 1515, Roswell, New Mexico 88201</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>A</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>17</b> TOWNSHIP <b>1-S</b> RANGE <b>36-E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4013' GL</b>	12. County <b>Roosevelt</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The captioned well was plugged and abandoned on May 24, 1969, in the following manner with all cement plugs set in heavy mud:

25 sacks @ Top of Glorietta @ 3886-3929'  
25 sacks @ Top of San Andres @ 2522-2608'  
25 sacks @ Base of Salt @ 1712-1798'  
25 sacks @ Top of Salt @ 1430-1516'  
25 sacks in-and-out of 8-5/8" surface casing @ 447-528'  
10 sacks @ surface @ 0-38'

A regulation dry hole marker was erected and the location cleaned up.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harry P. Schram TITLE Manager DATE May 25, 1969  
APPROVED BY John W. Remyer TITLE Manager DATE May 27, 1969  
CONDITIONS OF APPROVAL, IF ANY: