

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

0533777-B

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Jenkins-Dhaenens Oil Company, Inc.		8. FARM OR LEASE NAME Shell Federal	
3. ADDRESS OF OPERATOR c/o Hobbs Pipe & Supply Co., Box 2010, Hobbs, N. M. 88240		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  1980' FSL & 1980' FWL		10. FIELD AND POOL, OR WILDCAT Cheveroo	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 23-7-32	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4457' GR		12. COUNTY OR PARISH Roosevelt	
		13. STATE N. M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☒  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐

REPAIRING WELL

☐  
☐  
☐  
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Spot a 25 sx plug to cover existing perforations.
2. Load hole w/mud-laden fluids.
3. Shoot casing @ approx. 1,000' & spot a 25 sx plug.
4. Spot a 35 sx plug @ base of surface pipe, 400'.
5. Spot a 10 sx plug @ top of hole, & erect a 4" regulation marker.

**AMENDMENT:**

Spot additional 25 sack cement plug inside pipe at 1800-2100'.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Stanley Sarkin*

TITLE

AGENT

DATE

4/23/73

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

**APPROVED**

APR 26 1973

ARTHUR R. BROWN  
DISTRICT ENGINEER

\*See Instructions on Reverse Side