

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
9. Well No.	
10. Field and Pool, or Wildcat	
12. County	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	2. Name of Operator	3. Address of Operator	4. Location of Well
	William K. Young	750 West Fifth Street, Ft. Worth, Texas 76102	UNIT LETTER <u>M</u> . <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>20</u> TOWNSHIP <u>6-S</u> RANGE <u>37-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)			
GR 4045			

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5 November 1973

Well has been drilled w/7 7/8' bits from 8 5/8 shoe @3415 to T. D. of 8350'. Cement plugs to be spotted by Halliburton as follows:

50 Sx. - 7872 - 7772 - Across top of Granite.
50 Sx. - 6730 - 6630
50 Sx. - 4742 - 4642
50 Sx. - 3440 - 3340

Shoot off 8 5/8" casing @ 1040' and pull same.

Plugs as follows:

80 Sx. - 1100 - 990
100 Sx. - 400 - 270
10 Sx. - in surface pipe at top.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. H. Dinsmore TITLE District Supt. DATE 11/23/73

APPROVED BY Nathan E. Begg DATE _____

CONDITIONS OF APPROVAL, IF ANY: