

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>William K. Young</b>	8. Farm or Lease Name <b>D. B. Lieb, et al</b>
3. Address of Operator <b>750 West Fifth Street, Ft. Worth, Texas 76102</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>M</b> , <b>660</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>20</b> TOWNSHIP <b>6-S</b> RANGE <b>37-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>GR 4045</b>	12. County <b>Roosevelt</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**5 November 1973**

Well has been drilled w/7 7/8" bits from 8 5/8 shoe @3415 to T. D. of 8350'.  
Cement plugs to be spotted by Halliburton as follows:

50 Sx. - 7872 - 7772  
50 Sx. - 6730 - 6630  
50 Sx. - 4742 - 4642  
50 Sx. - 3440 - 3340

**50 Sx 2+ T.D.**

Shoot off 8 5/8" casing @1040' and pull same.

Plugs as follows:

80 Sx. - 1100 - 990  
100 Sx. - 400 - 270  
10 Sx. - in surface pipe at top.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *A. H. Simon* TITLE District Supt. DATE 11-8-73

APPROVED BY John P. Gooch TITLE  DATE   
CONDITIONS OF APPROVAL, IF ANY: