## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we. er comice acceives	ļ	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		ĺ
LAND OFFICE		
OPERATOR		

O+4-NMOCD, H 1-Hou

## IL CONSERVATION DIVISIOI.

Form	C - 1	03	
Revis	e d	10-	1 - 7

DISTRIBUTION P. O. BOX 2088	Form C-103 · Revised 10-1-78
SANTA FE SANTA FE, NEW MEXICO 87501	
FILE	5a, Indicate Type of Lease
U.S.O.S.	State For X
OPERATOR	5, State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
USE "APPLICATION FOR PLEMIT - FORM CTIOTY FOR SUCH PROPERTIES."	7. Unit Agreement Name
oil GAR OTHER- Salt Water Disposal	Peterson Penn Storage Sy
2. Name of Operator	8. Farm or Lease Name
Amoco Production Company	Swearingen "C"
J. Address of Operator	9, Well No.
P. O. Box 68 Hobbs, NM 88240	2 10. Field and Pool, or Wildcat
4. Location of Well	Fusselman
UNIT LETTER M . 330 FEET FROM THE SOUTH LINE AND 990 FEET FROM	Luzzeman
THE West LINE, SECTION 18 TOWNSHIP 5-S RANGE 33-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	Roosevelt
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
	REPORT OF:
NOTICE OF INTENTION TO	
PERFORM REMEDIAL WORK X	ALTERING CASING
TEMPORABILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.	
n	
Propose to decrease injection pressure by the following method:	
Acidize fusselman perfs (8313'-18', 8334'-44', and 8448'-	54')
with 3000 gallons 15% HCL acid. Return well to injection	-
Witch 5000 garrons 70% not dotal Notari not 100 and	
•	
is. I hereby certify that the information shove is true and complete to the best of my unowledge and belief.	
Manual Color Assist. Admin. Analyst	5-9-80
SIGNED VITLE ASSIST. AUDITI. ANALYST	. DATE
	2 x 2 4000
Orig. Signed by	DATE 9977 1 1000
APPROVED BY John Runyan	