

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20471
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Lambirth A
8. Well No. 1
9. Pool name or Wildcat Peterson South Fusselman

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4411.1' GR; 4416.1' RKB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

4. Well Location
Unit Letter J : 1980 Feet From The East Line and 2055 Feet From The South Line
Section 31 Township 5-S Range 33-E NMPM Roosevelt County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Cleaned out and acidized <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-27-93 - Sub pump out of hole. Iron and scale found on tubing and pump assembly. BOP on wellhead. GIH w/2-7/8" and a 4-3/4" bit on scraper to 7840'. COOH.

8-30-93 - GIH w/pkr. on 2-7/8" to 7750'. Set pkr. and load back side. Press. up on back side to 500 psi. Swab.

8-31-93 - Perfs: 7830-7838'. Pump down tubing w/1000 gals 15% NeFe.

9-01-93 - Release pkr. and COOH. GIH w/2-7/8" and sub pump. ND BOP. Flange up wellhead. Put well pumping to Battery.

9-05-93 - 24-Hour Test: 44.7 BO; 7,392 BW; 901 GOR.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supv. Regulatory Affairs DATE 09-13-93
TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. (915) 368-1488

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE SEP 17 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 13 1993

**COAST GUARD
OFFICE**