


**ENSERCH
EXPLORATION** INC

ClayDesta National Bank Bldg.
Suite 5250
6 Desta Drive
Midland, Texas 79705
915-682-9756

May 6, 1991


Leonard Kersh
District Production Manager
Dane Hendley
District Petroleum Engineer
George Faigle
District Development Geologist
Sammy Reed
Production Superintendent
West Texas/Rocky Mountain District
Production Division

Mr. Jerry Sexton
OCD District I Supervisor
State of New Mexico
Energy, Minerals and Natural resources Department
Post Office Box 1980
Hobbs, New Mexico 88241-1980

Dear Mr. Sexton,

Enserch Exploration, Inc., as the managing general partner of EP Operating Co., received notification of the implementation of the new Order No. R-9210. Included with the notification was a list of wells that, according to your records, have not produced in over a year. The well on our list was the Lambirth No. 7 which is located in Unit Letter P: 660 feet from the East line and 510 feet from the South line of Section 30, Township 5S, Range 33E NMFM in Roosevelt County, New Mexico. In April of 1985, the Lambirth No. 7 was recompleted from the Peterson; Fusselman, South to the Peterson; Penn. Assoc., South where it produced until April of 1990 when the Pennsylvanian and Fusselman were commingled and reported in the Peterson; Penn. Assoc., South Field.

Included is a copy of the last Form C-103 and C-104 that were filed at the time of commingling in April of 1990 and were approved in May of 1990 by your department. Please advise if there are any further details that need to be qualified to remove this well from the non-producing list.


Wm. Dane Hendley
District Petroleum Engineer

TRR:
Attachments