

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Salt Water Disposal		7. Unit Agreement Name
2. Name of Operator Enserch Exploration, Inc.		8. Farm or Lease Name Lambirth
3. Address of Operator P. O. Box 4815, Midland, Texas 79704		9. Well No. 5
4. Location of Well UNIT LETTER <u>N</u> <u>1890</u> FEET FROM THE <u>West</u> LINE AND <u>660</u> FEET FROM THE <u>North</u> LINE, SECTION <u>1</u> TOWNSHIP <u>6S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or Wildcat So. Peterson Fusselman
15. Elevation (Show whether DF, RT, GR, etc.) 4421.6' GR		12. County Roosevelt

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned on 9/2/80 as follows:

Set CIBP at 7790' w/35' of Class "H" cement from 7755' to 7790'.
Set CIBP at 7680' w/35' of Class "H" cement from 7645' to 7680'.
Set CIBP at 4790' w/35' of Class "H" cement from 4755' to 4790'.
Cut off 5-1/2" casing at 2500'.
Laid 100' Class "H" cement plug from 2450' to 2550'.
Laid 100' Class "H" cement plug from 1949' to 2049'.
Laid 10 sack plug at surface.
Cut off 8-5/8" casing head and welded steel plate on 8-5/8" casing.
Installed dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. F. Burnett TITLE Production Superintendent DATE 9/10/80

APPROVED BY W. L. Patterson TITLE Assistant Commissioner DATE 9/10/80

CONDITIONS OF APPROVAL, IF ANY: