

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20514
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-5048
7. Lease Name or Unit Agreement Name Lambirth State
8. Well No. 1
9. Pool name or Wildcat Peterson Fusselman South
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 4400'

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator EP Operating Limited Partnership
3. Address of Operator 6 Desta Drive, Suite 5250, Midland, TX 79705-5510

4. Well Location Unit Letter H : 1980 Feet From The North Line and 510 Feet From The East Line Section 36 Township 5S Range 32E NMPM Roosevelt County
-------------------------------------------------------------------------------------------------------------------------------------------------------------

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Convert to SWD <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to move in and rig up workover unit. POH and lay down rods. NU BOP. POH and lay down tubing. RU wireline truck. RIH with gauge ring and junk basket to 8000'. POH. RIH with perforating gun and add perforations from 7830'-48', 4 JSPF, to existing perforations from 7796'-7806'. POH. RIH with lined tubing and packer. Set packer at  $\pm$  7750'. Test casing and packer to 500# for 30 minutes. Acidize well with 5000 gallons 20% HCL acid. Hook up surface equipment for disposal of salt water. Proposed starting date February 1, 1994.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE S. D. Reed TITLE Production Superintendent DATE 01/14/94

TYPE OR PRINT NAME S. D. Reed TELEPHONE NO. (915) 682-975

(This space for State Use)

**ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR**

**JAN 21 1994**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: