OF COPIES RE	CELVED	7						Form C-101		•
		-				~ ,		Supersedes C-102 and C		
DISTRIBUT	ION	, NE	W MEXICO OIL	CONSE	RVATION C	OMMISSION .		Effective 1-		
SANTA FE		-	" MEXICO OIL							
FILE							[:	a. Indicate Ty		$\overline{\Box}$
U.S.G.S.		4						State	Fe	e X
LAND OFFICE		-						S. State Cil & C	as Lease No.	
OPERATOR								N/M =	2052	1
								THITT	THIN.	TTT
	SUND	RY NOTICES	AND REPOR	TS ON	WELLS	ENT RESERVOIR.				/////
(DO NOT U	SE THIS FORM FOR PI USE "APPLICA	ROPOSALS TO DRILL TION FOR PERMIT	- " (FORM C-101)	FOR SUC	PROPOSALS.I			7. Unit Agreem	ent Name	7777
1.								r, come organis		
well X	GAS WELL	OTHER-						e, Farm or Lea	ca llame	
Name of Cherator								Shell Bru		1
SHELL	OIL COMPANY		_					9. Well No.		<u> </u>
Address of Over	ator			<u>-</u>				9. Well No.		
P. 0.	BOX 991, HO	USTON, TX 7	77001					<u> </u>		
4. Location of Well						1000	1	10. Field and F	ool, or wilded	T.
4. Eocation	XX	2310	FROM THE	outh	LINE AND	1980 	EET FROM	Wildcat	mm	\overline{m}
UNIT LETTER _									////////	
Eas	t. v	34	TOWNSHIP	48	BANGE	34E	NMPM.			/////
THE	LINE, SEC								777777	77777
mm	mm	.51	Elevation (Show	whether	DF, RT, GR, e	tc.)	1	12. County		./////
			4329.8'			•		Roosevelt	7////	77777
7////////		777777			f Na	nias Papas	e or Othe	r Data		
ıů.		Appropriate		icate N	ature of No	itice, Kepor	COLENT	REPORT OF	= •	
	NOTICE OF	INTENTION T	ro:			20825	QUENT	REPORT OF	•	
									ERING CASING	
PERFORM REMEDIA	L WORK		PLUG AND ABAN	DON []	REMEDIAL WO		H		AND ABANDONA	M
TEMPORARILY ABAI						IILLING OPNS.		PLUC	, AND ABANDONA	4EM1 (1/3)
PULL OR ALTER CA	f 1		CHANGE PLANS	الـا	CASING TEST	AND CEMENT JQB				
	_				OTHER					
OTHER										
i7. Describe Frop				i dass	ile and give t	nertinent dates.	including e	stimated date of	of starting any	proposed
i7. Describe From	osed or Completed	Operations (Clear	rly state all pert	ment der	itis, una give p		_			
4-5-80:	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,									
	6 1/2 hr p	lug well &	lav down I	OP: 10	1/2 hrs	BOP: 7 hr	clean	mud pits.		
6 1/2 hr plug well & lay down DP; 10 1/2 hrs BOP; 7 hr cles Plug #1 @8950-8850 35 sx, Plug #2 @7800'-7700', 35 sx, Plug								g #3 @6720-6620 '		
50 sx, Plug #4 @3452' - 3352' 50 sx, Plug #5 @1800' - 1700'										
	Plug #6 @3	o'-surface.	10 sx cm	used	was Clas	s H + 4/1	0 of 1%	CFR2 and	mixed	
		w/yield of								
	C13.0"/ Bar	w/ y leid of	1.20.							
4-6-80:										
4-0-50.	l hr clean	mud nite	Pig Polose	~od 07	·00 a m	CST 4-5-8	Λ			
	I III Clean	mad pics,	Kig Keleas	seu er	.00 а.ш.	031 4 3 0	•			
•										
		,								
		•								
	fy that the informat	ton whome to term	and complete to	the best	of my knowled	ge and belief.				
if. I hereby certification	ly that the informat	, on acove is true	and a dispersion of							
	<u> </u>		EUDE	ς	R. ENGR.	TECH.		4	1-10-80)
SIGNED &	Zu	<u> </u>	FORE	TLE	LITUITA			7		=
	6 G. J.	,		f	1. & GA	S LOVE PULL	Contract Contract			
AMPROVED BY	1. H. Slots	t-2000 1100	T [TLE		-		DATE		

CONDITIONS OF APPROVAL, IF ANY: