

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

API No. 30-041-20525

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
Name of Operator Phillips Petroleum Company			5. State Oil & Gas Lease No. ---
Address of Operator Room 401, 4001 Penbrook, Odessa, Texas 79762			7. Unit Agreement Name
Location of Well UNIT LETTER <u>M</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>5-S</u> RANGE <u>33-E</u> N.M.P.M.			8. Farm or Lease Name Lambirth A
			9. Well No. 5
			10. Field and Pool, or Wildcat Peterson Fusselman South
15. Elevation (Show whether DF, RT, GR, etc.) 4361.8 GR 4391 DF			12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Plug back to Penn.</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull tbg and pkr.
GIH w/tbg and retainer. Set retainer at 7800'±.
Squeeze perms 7828'-7844' and 7846-7854' w/100 sx's of 15.6#/gal Cl "H" cmt. Pull
out of retainer and reverse out cmt. Fusselman zone abandon w/sufficient cmt.
Prepare to complete in Pennsylvania zone.

BOP equipment: Series 900, 3000# WP, double w/one set pipe rams and one set blind rams.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed W. J. Mueller TITLE Senior Engineering Specialist DATE April 21, 1980
Orig. Signed by John Runyan
Geologist TITLE _____ DATE _____
APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY: