N . OF CAPITS RECLIVED		Form C-103 Supersedes Old C-102 and C-103		
SANIA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65		
1 N. F		Sc. Indicate Type of Lease		
1.5.G. <b>S</b> .		State Fee X		
AND OFFICE		5. State Cil & Gas Lease No.		
UPERATOR		J. State Ch. & Gas Lease No.		
SUNDRY	Y NOTICES AND REPORTS ON WELLS			
UD NOT USE THE TAPPLICATIO	ON FOR PERNIT - " (FORM C-101) FOR SUCH PREPOSALS.)	7. Unit Agreement Name		
CIL GAS GAS WELL	OTHER- Dry			
Nine of Operator		8, Farm or Lease Name		
Coquina Oil Corporation	Clemmons			
A cirees of Creater		9. Well No.		
P. O. Drawer 2960, Midl	1			
Location of Well	10. Field and Pool, or Wildcat			
С. 6	560 FEET FROM THE North LINE AND 1980 FEE	Wildcat		
UNIT LETTER	FEET FROM THETOLOTT LINE AND FOR			
THE West LINE, SECTION	n 10 township 6S range 32E	_NIAPM. ())))))))))))))))))))))))))))))))))))		
THE Chief Stort 1				
15. Elevation (Show whether DF, RT, GR, etc.)		12. County		
	4480' RKB	Roosevelt		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN	QUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK [ COMMENCE DRILLING OPNS. [ CHANGE PLANS CASING TEST AND CEMENT JQB	ALTERING CASING		
OTHER	OTHER			
.7. Describe Proposed or Completed Op work) SEE RULE 1103.	verations (Clearly state all pertinent details, and give pertinent dates, ir	ncluding estimated date of starting any proposed		
Started completion atte	empt on 8/22/80. Perfed 7978-90'; acidized	w/1500 gals, swabbed 22 bbls		

salt water. Set CIBP @7900'. Dumped 13' cmt on CIBP. Perfed 7772-90', acidized w/2000 gals, swabbed 24 bbls salt water. Set CIBP @ 7750'. Dumped 13' cmt on CIBP. Perfed 7658-69', acidized w/1500 gals, swabbed dry. Set CIBP @ 7650'. Dumped 10' cmt on CIBP. Perfed 7620-25', acidized w/1000 gals, swabbed dry. Set CIBP @ 7600'. Dumped 13' cmt on CIBP. Perfed 7620-25', acidized w/1000 gals, swabbed dry. Set CIBP @ 7600'. Dumped 13' cmt on CIBP. Perfed 7620-25', acidized w/1500 gals, swabbed 5 bbls salt water. Set CIBP @ 7517'. Dumped 5' cmt on CIBP. Perfed 7446-7507', acidized w/4000 gals, swabbed dry. Set CIBP @ 7350'. Dumped 11' cmt on plug. Perf 7104-7222', acidized w/4000 gals, swabbed dry. Set CIBP @ 7093'. Dumped 10' cmt on CIBP. Perf 7023-66', acidized w/3000 gals, swabbed 12 bbl salt water. Set CIBP @ 7000'. Dumped 11' cmt on CIBP. Perf 5060' for squeeze. Squeezed w/75 sxs Cl. C. Ran temperature survey. TOC 4900'. Perf 5021-32', acidized w/100 gals & had communication w/5 1/2" annulus. Squeezed 5021-32' w/75 sxs Cl. C. Cleaned out cmt. Re-perf 5021-32', acidized w/100 gals, swabbed 24 bbls salt water. All zones were noncommercial.

Prep to set CIBP @ 5000' & dump <sup>35</sup>' cmt on plug. Will cut off 5 1/2" csg @ 4900' & pull csg. Will spot cmt plugs from 4950-4850', 3150-3050', & 50-3'. Hole will be loaded w/9 ppg mud ladden fluid. Will install dry hole marker to complete P&A operations. P&A operations should begin on November 17, 1980.

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
There the my Mars. a	TITLE	Operations Manager	DATE 11/5/80	
	T ! T \. E		DATE	
ONDITIONS OF APPROVAL, IF ANY:			- 1. 17. 17. 17. 17. 17. 17. 17. 17. 17.	