Submit 3 Contes	New Mexico atural Resources Department	Form C-103 Revised 1-1-89
P.O. Box 1980, Hobbs, NM 88240 P.O.	ATION DIVISION Box 2088	WELL API NO. 30-041-20531
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New I	Mexico 87504-2088	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No. L-4401
SUNDRY NOTICES AND REPORTS	ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DIFFERENT RESERVOIR. USE "APPLICATION (FORM C-101) FOR SUCH PROPOSA	DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OL CAS WELL X WELL OTHER		Amoco State
2. Name of Operator EP Operating Company		8. Well No.
3. Address of Operator		9. Pool name or Wildcat
6 Desta Drive, Suite 5250, Midland, TX 4. Well Location	79705-5510	North Peterson (Penn)
Unit Letter : Feet From The	h Line and 660	Feet From The West Li
Section 16 Township 4S		NMPM Roosevelt County
///////////////////////////////////////	w whether DF, RKB, RT, GR, etc.) 7.7' GR	
11. Check Appropriate Box to In		Leport, or Other Data
NOTICE OF INTENTION TO:		SEQUENT REPORT OF
		_
		ALTERING CASING
		<u> </u>
		G OPNS. DUG AND ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS		
	COMMENCE DRILLING CASING TEST AND CI	G OPNS. PLUG AND ABANDONMENT
CHANGE PLANS CHANGE PLANS CULL OR ALTER CASING CHANGE Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103. Proposed plugging procedure to commence Retainer previously set at 6650' and sq Lay 15 sack cement plug from 2950'-3050 Perforate 5½'' casing at 2085'. Set ret Dump 35' of cement on top of retainer. Cut off wellhead. Lay 10 sack plug from 30' to surface. Install dry hole marker.	COMMENCE DRILLING CASING TEST AND CO OTHER: details, and give pertinent dates, inclu approiximately 10/1, ueezed w/50 sacks cen '. ainer at 2035'. Sque	G OPNS. PLUG AND ABANDONMENT EMENT JOB
EMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING DTHER: DTHER:	COMMENCE DRILLING CASING TEST AND CO OTHER: details, and give pertinent dates, inclu approiximately 10/1, ueezed w/50 sacks cen '. ainer at 2035'. Sque	G OPNS. PLUG AND ABANDONMENT EMENT JOB
EMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING D DTHER:	COMMENCE DRILLING CASING TEST AND CO OTHER: details, and give pertinent dates, inclu approiximately 10/1, ueezed w/50 sacks cen '. ainer at 2035'. Sque	G OPNS. PLUG AND ABANDONMENT EMENT JOB
EMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING D DTHER:	COMMENCE DRILLING CASING TEST AND CL OTHER: details, and give pertinent dates, inclu approiximately 10/1, ueezed w/50 sacks cen '. ainer at 2035'. Sque	G OPNS. PLUG AND ABANDONMENT EMENT JOB
EMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING D DTHER:	COMMENCE DRILLING CASING TEST AND CL OTHER: details, and give pertinent dates, inclu approiximately 10/1, ueezed w/50 sacks cen '. ainer at 2035'. Sque	G OPNS. PLUG AND ABANDONMENT EMENT JOB date of starting any proposed /90: nent. eeze w/75 sacks.