

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry hole</u>	7. Unit Agreement Name
2. Name of Operator <u>Arbusto Energy, Inc.</u>	8. Farm or Lease Name <u>Moore</u>
3. Address of Operator <u>1610 North J, Midland, Tx 79701</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>F</u> 1980 FEET FROM THE <u>North</u> LINE AND 1980 FEET FROM THE <u>West</u> LINE, SECTION <u>8</u> TOWNSHIP <u>6-S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat <u>Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4386.5' GR</u>	12. County <u>Roosevelt</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notified District Office of intent to plug & received plugging instructions on 10/26/80. Commenced plugging operation 10/27/80.

Set bridge plug @ 3848'. Set a 35' cement plug @ 3846', a 100' cement plug @ 1500' and a 10' surface plug in the 8 5/8" casing. 10.2# mud was used while plugging. Set dry hole marker and dressed location. Plugging complete 10/28/80.

413' of 12 3/4" casing and 4232' of 8 5/8" casing were left in well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Neal A Taylor</u>	TITLE <u>Agent</u>	DATE <u>11/18/80</u>
APPROVED BY <u>Ronald M. [Signature]</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JAN 12 1983</u>
CONDITIONS OF APPROVAL, IF ANY:		