

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-041-20558

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
ENSERCH EXPLORATION, INC.

3. Address of Operator  
6 DESTA DRIVE SUITE 5250, MIDLAND TX 79705-5510

4. Well Location  
Unit Letter J : 1980 Feet From The SOUTH Line and 1980 Feet From The EAST Line

Section 6 Township 5S Range 33E NMPM ROOSEVELT County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
4505.8' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. UNSEAT PUMP, POH, LAY DOWN RODS & PUMP.
  2. RELEASE TAC, POH W/TBG.
  3. RIH, SET CIBP @ 8100'. CIRC. HOLE W/MUD LADEN FLUID. SPOT 5 SX. CMT ON TOP OF CIBP.
  4. SPOT 25 SX PLUG FROM 6550' TO 6350'.
  5. FREE PT. AND CUT 5-1/2" CSG @ APPROX. 3500'. POH & LAY DOWN CSG.
  6. SPOT 30 SX CMT. PLUG FROM 50' INSIDE 5-1/2" STUB TO 50' ABOVE STUB IN 8-3/4" OPEN HOLE.
  7. SPOT 40 SX. CMT. PLUG FROM 3100' TO 3000' IN 8-3/4" OPEN HOLE.
  8. SPOT 45 SX CMT. PLUG FROM 2047' IN 8-3/4" OPEN HOLE TO 1947' IN 9-5/8" CSG. WOC, TAG THIS PLUG
  9. SPOT 35 SX CMT. PLUG FROM 400' TO 300' IN 9-5/8" CSG.
  10. CUT OFF 9-5/8" CSG. HEAD.
  11. SPOT 10 SX SURFACE PLUG.
  12. WELD ON PLATE, INSTALL DRY HOLE MARKER.
- PROPOSED STARTING DATE IS 10-1-95 DEPENDING ON AVAILABILITY OF PLUGGING RIG.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve Hartley TITLE PROD. SUPV. DATE 8-24-95

TYPE OR PRINT NAME STEVE HARTLEY (915) TELEPHONE NO. 682-9756

(This space for State Use)

Orig. Signed by  
Paul Wertz  
8-24-95

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103