

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

File In Quadruplicate  
OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

cc: F. Wheeler  
Partners (3)

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Exploration Wildcat	7. Unit Agreement Name
2. Name of Operator Sun Oil Company (Delaware)	8. Farm or Lease Name J. McClellan
3. Address of Operator P.O. Box 30, Dallas, TX	9. Well No. #1
4. Location of Well UNIT LETTER <u>AK</u> 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>6-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat Undesignated (Granite) <sup>Wa</sup>
15. Elevation (Show whether DF, RT, GR, etc.) 4399 GR	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:


PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Plug back test zone

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set CIBP at 7760' on wire line to plug off perforations 7790' - 7800'.
- Dumped 35' of cement on Bridge Plug, PB depth 7725'.

NOTE: Reference C-103 filed 7-21-81.

Dumped additional 1½ sx cmt on bridge plug, for total of 40' cmt now on plug  
@ 7950, with PB depth at 7910'.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE Operations Engineer	DATE 8-5-81
APPROVED BY <u>Jerry Saxton</u>	TITLE <u>Dist. L. Saxton</u>	DATE <u>AUG 10 1981</u>
CONDITIONS OF APPROVAL, IF ANY:		