

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Enserch Exploration, Inc.	8. Farm or Lease Name Franse
3. Address of Operator P. O. Box 4815, Midland, Texas 79704	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>2130</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>4S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat Peterson Mississippian
15. Elevation (Show whether DF, RT, GR, etc.) 4337.7 GR	12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plans are to plug and abandon well within 30 days as follows:

Set CIBP at 4090' with 35' Class H cement from 4065' to 4090'.
Cut off 5-1/2" casing at 3600'.
Lay 25 sack Class H cement plug from 3550' to 3650'.
Lay 40 sack Class H cement plug from 1965' to 2065'.
Lay 10 sack Class H cement plug at surface.
Cut off 9-5/8" casinghead.
Weld steel plate to 9-5/8" casing.
Install dry hole marker.

100' plug @ 1606'

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE SIGNING OF ANY PLUGGING ORDER FOR THE C-103.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H.F. Burnett H.F. Burnett TITLE Production Superintendent DATE 7/19/82

ORIGINAL SIGNED BY

APPROVED BY JERRY SEXTON

CONDITIONS OF APPROVAL DISTRICT AN SUPR.

TITLE

DATE

AUG 2 - 1982