

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-D41-20624
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name ENSEARCH STATE
2. Name of Operator COLTER OPERATING, INC.	8. Well No. 1
3. Address of Operator PO Box 7671 Horseshoe Bay TX 78654	9. Pool name or Wildcat PETERSON NORTH PENN
4. Well Location Unit Letter J : 2086' Feet From The S Line and EL 2086 Feet From The E Line Section 16 Township 4-S Range 33E NMPM ROOSEVELT County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. SET CIBP @ 7960', PLUS 35' OF CMT
2. LOAD HOLE W/ 10# BRINE
3. FREEPOINT 4-1/2" CSG. CUT & LAY DOWN @ 5500' EST.
4. 25 SX "C" STUB PLUG - WOC TAG PLUG LOAD HOLE W/ MUD.
5. 25 SX "C" 4960' - 4860'
6. 35 SX "C" 4420' - 4320' GLORIETTA
7. 50 SX "C" 2068' - 1968' ANHYDRITE & 8-5/8" SHOE WOC TAG PLUG
8. 80 SX "C" 404' - 304' 13-3/8" SHOE WOC TAG
9. 10 SX "C" SURFACE
10. CUT OFF WELLHEAD INSTALL DRY HOLE MARKER

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry Murray TITLE RIG SUPERINTENDENT DATE 8-4-95
TYPE OR PRINT NAME LARRY MURRAY TELEPHONE NO. (915)683-97

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE AUG 14 1995
CONDITIONS OF APPROVAL, IF ANY: