

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.
Fee Land

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

6. Fil ☒ WELL ☐ GAS WELL ☐ OTHER ☐
Name of Operator
Jonas Consultants
Address of Operator
P.O. Box 937, Artesia, New Mexico 88210
Location of Well
UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM East THE LINE, SECTION 32 TOWNSHIP 4S RANGE 33E

7. Unit Agreement Name

8. Farm or Lease Name
Richardson

9. Well No.
#1

10. Field and Pool, or Whidear
UNDESIGNATED

15. Elevation (Show whether DF, RT, GR, etc.)
4414 GR

12. County
Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

INFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING JOBS ☐	PLUG AND ABANDONMENT ☐
WELL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103

Cut 5 1/2" casing at 3989' with 4 7/16" O.D. casing cutter. FCOH with 98 jts of 5 1/2" casing. Went back in hole with 2 7/8" tubing to 8270' to plug and abandon.

Plugged as follows 2-9-83, with total of 228 sacks Class C Neat cement.

Plug #1 20 sxs (202' plug, inside 5 1/2" casing) 8270' to 8068'. PD 6:00 a.m.
Plug #2 20 sxs (202' plug, inside 5 1/2" casing) 7350' to 7148'. PD 7:35 a.m.
Plug #3 20 sxs (202' plug, inside 5 1/2" casing) 6646' to 6444'. PD 9:00 a.m.
Plug #4 50 sxs (150' plug) 4030' to 3900'. Top of 5 1/2" casing 3989'. PD 11:30 a.m.. Pulled up to 3900' polish off top of plug. Circulated cement back to surface.
Plug #5 50 sxs (100' plug) 3170' to 3070'. PD 1:30 p.m.
Plug #6 50 sxs (100' plug) 2060' to 1960'. 8 5/8" casing 2010'. PD 3:30 p.m. Pulled up to 1960' polish off top of plug. Circulated cement to surface.
Plug #7 18 sxs 60' to surface. PD 5:30 p.m.

Hole already loaded with 10% brine between plugs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Barbara Jonas TITLE Co Owner DATE 2-11-83
APPROVED BY Elder W. Swan TITLE OIL & GAS INSPECTOR DATE NOV 17 1983
CONDITIONS OF APPROVAL, IF ANY: