OPIC	ENRY SEXTON			
GNED	rey E. Lango		rporation Presid	ent DATE
3-15-82	well. Plugg commission o	4 1/2 production ing procedure n following C-	calculated & app 103.	sion made to plug proved by oil
3-12-82	LOG.			D.S.T. & SCHLUMBERGER
2 - 7-82	Cut off 8 5/8 casing and weld on 9 5/8 X 900 series flange- nippleup B.O.P test casing to 1500#. Held for 30 minutes. Drill ahead with 7 7/8 bit.			
2-6-82	Ran 48 joints 8 5/8 24# K-55 ST&C. R-3 casing set at 2010'. Cement with 1100 sacks class C with 2% CACL. Pump plug to 1968' with fresh water. Full returns on circulated cement. Circulated out 160 sacks to pit. W.O.C 18 hours.			
2-5-82	Drill 12 1/4	hole to 2010'		
7. Describe Proposed or work) SEE RULE 110		learly state all pertinent det	ails, and give pertinent dates,	including estimated date of starting any pro
OTHER		<u>·</u>		
PULL OR ALTER CASING	L	CHANGE PLANS	CASING TEST AND CEMENT JOB	
TEMPORARILY ABANDON	Ĭ	*	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMEN
NO	TICE OF INTENTIO		· · · · · ·	EQUENT REPORT OF:
6. 6.		G.L. 4399.9 ate Box To Indicate N	lature of Notice, Repor	Roosevelt
		TOWNSHIP 15. Elevation (Show whether	د	
			LINE AND 33 E	
Location of Well T 1980 South 1980				10. Field and Pool, or Wildcat Peterson Mississi
Address of Operator P.O. Box 1182, Hobbs, New Mexico 88240				9. Well No. 1
Pri-State Production & Supply Inc.				Richardson
OIL CAB OTHER-				8. Farm of Lease Name
(DO NOT USE THIS U	FORM FOR PROPOSALS TO D	ES AND REPORTS ON DECEMENT OF TO DECEMENT OF TO DECEMENT OF TO BE SUC	ACK TO A DIFFERENT RESERVOIR.	
OPERATOR				5. Staje Off & Gas Leuse No.
U.S.O.S. LAND OFFICE				Sa. Indicate Type of Lesse State Fee
SANTA FE FILE		SANTA FE, NEW	MEXICO 87501	Revised 10
Distritiserieit	N OIL CONSERVATION DIVISION P. O. BOX 2088			
DISTRIBUTION	1			Form C-103

•

O.C.D. HOBBS OFFICE

MAY 31982

received