

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator Cities Service Company		8. Farm or Lease Name May A
3. Address of Operator P.O. Box 1919 - Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 1 TOWNSHIP 2S RANGE 33E NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4079' GR		12. County Roosevelt

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. 7450' Granite Wash. It is proposed to plug and abandon this well in the following manner:

1. RIH w/open ended DP and circulate hole w/mud laden fluid. Spot a 50 sack cement plug @ approx. 7357 - 7138', across the top of the Granite. LDDP to 6415'.
2. Spot a 50 sack cement plug @ approx. 6415 - 6298', across the top of the Wolfcamp. LDDP to 5168'.
3. Spot a 50 sack cement plug @ approx. 5168 - 5038', across the top of the Tubb. LDDP to 3725'.
4. Spot a 50 sack cement plug @ approx. 3725 - 3598', across the top of the Glorita. LDDP to 2694'.
5. Spot a 50 sack cement plug @ approx. 2694 - 2568', across the top of the of the San Andres and half in and half out of the 8-5/8" casing shoe @ 2637'. LDDP to 1508'.
6. Spot a 35 sack cement plug @ approx. 1508 - 1375'. LDDP.
7. Dump a 10 sack cement surface plug @ approx. 20 - 0'. Install a dry hole marker to designate a plugged and abandoned location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elmer Stantz TITLE Reg. Opr. Mgr. - Prod. DATE 1-10-83

APPROVED BY ORIGINAL SIGNED BY TITLE JERRY SEXTON DATE JAN 17 1983
CONDITIONS OF APPROVAL, IF ANY: DISTRICT 1 SUPR.