

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2084

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO ABANDON, PLUG, OR DRILL A WELL, OR TO A DIFFERENT RESERVOIR.
SEE APPLICATION FOR PLUG AND ABANDON, OR DRILL, FOR A DIFFERENT RESERVOIR.)

WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Western Oil Producers, Inc.

Address of Operator

P.O. Box 1498, Roswell, New Mexico 88201

Location of Well

THIRD LETTER F 1930 North 1980 FEET FROM

West 30 5 34 FEET FROM

1. Inventory (Plug, Abandon, E, FT, GR, etc.)
4222.85 GR

1a. Indicate Type of Lease State ☐ Fee ☒
3. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Name of Lease Owner Radcliff
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
11. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

REPAIR ABANDON WORK ☐
ABANDON WORK ☐
ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPER. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give precise dates, including estimated date of starting any proposed work. SEE RULE 1103.)

TD-8250'

Prepare to use drilling rig to plug well, spot cement plugs as follows:

100' plug 8140'-8240'
100' plug 7196'-7296'
100' plug 6639'-6739'
100' plug 4574'-4674'
100' plug 3226'-3326'
100' plug 2450'-2550'
50' plug in and out 8 5/8
10 sx plug @ surface
cut off well head

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

By Ronald Hewitt

TITLE Agent

DATE 5/23/83

MAY 31 1983

COPIES OF APPROVAL, IF ANY:

RECEIVED

MAY 31 1983

U.S.D.
HOBBS OFFICE