

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Howard XY
3. Address of Operator 105 S. 4th St., Artesia, N.M. 88210	9. Well No. 1-Y
4. Location of Well UNIT LETTER <u>M</u> <u>510</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM <u>West</u> LINE, SECTION <u>17</u> TOWNSHIP <u>7S</u> RANGE <u>32E</u> N.M.P.M.	10. Field and Pool, or WHdcat Tomahawk SA
15. Elevation (Show whether DF, RT, GR, etc.) 4470.2' GR	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well is no longer commercial to produce. We propose to plug and abandon as follows:

Spot 25 sx cement plug from PBTD to 100' above perfs. Spot 25 sx cement plug across top of San Andres (3444'). Cut & pull 4½" casing from about 3050'. Circulate hole with mud. Spot 35 sx cement plug across stub & tag. Spot 35 sx cement plug at top of salt at 1950-1850'. Spot 35 sx cement plug across 8 5/8" shoe at 1735-1635'. Spot 10 sx cement plug at surface w/dry hole marker. Clean location and ready for inspection.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie M. Matys TITLE Senior Engineer DATE 11-26-86

Orig. Signed by  
Paul Kautz

APPROVED BY Geologist TITLE  DATE DEC 3 1986

CONDITIONS OF APPROVAL, IF ANY: