

NO. OF COPIES RECEIVED	
DISTRIBUTION	
DATE	
FILE	
S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER-
Name of Operator
BHP Petroleum (Americas), Inc. 2217
Address of Operator
P.O. Drawer 2437, Midland, Texas 79702
Location of Well
UNIT LETTER C 660 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 18 TOWNSHIP 6S RANGE 34E NMPM.

7. Unit Agreement Name
8. Farm or Lease Name
Lambirth 1800
9. Well No.
1
10. Field and Pool, or Whicat
South Peterson Penn Assoc.
11. Elevation (Show whether DF, RT, GR, etc.)
4372.7 GR
12. County
Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) See attached "Completion Data Sheet" for well schematic.
- 2) These plugging operations will commence upon approval by partners. We estimate this will be in February, 1986.
- 3) We propose to plug and abandon the well as follows:
 - a) Set a CIBP at 7500' w/3 sx of cmt on top.
 - b) Load hole w/10# salt gel.
 - c) Spot 25 sx cmt across Glorieta at 6350'.
 - d) Shoot off csg above cmt plug at approximately 6000', and pull csg from well.
 - e) Spot 25 sx cmt across top of cut-off casing at 6000'. Leave 1/2 in and 1/2 out.
 - f) Spot 25 sx cmt across bottom of 8 5/8" csg at 3250'. Leave 1/2 in and 1/2 out.
 - g) Spot 25 sx cmt at 1800' inside 8 5/8" csg above salt section.
 - h) Spot 10 sx cmt at surface.
 - i) Weld on NMOCC approved P&A marker.

ALL INFORMATION MUST BE NOTIFIED TO
THE OIL CONSERVATION DIVISION AT THE BEGINNING OF
THE MONTH FOR THE YEAR 1986

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Michael L Jones TITLE Petroleum Engineer DATE 12/19/85

ORIGINAL SIGNED BY JERRY SEMON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE **DEC 23 1985**
CONDITIONS OF APPROVAL, IF ANY: