

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A		7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Durwood XW
3. Address of Operator 105 South 4th St., Artesia, NM 88210		9. Well No. 2
4. Location of Well UNIT LETTER 0 990 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 18 TOWNSHIP 7S RANGE 32E NMPM.		10. Field and Pool, or WHdcat Tomahawk SA
15. Elevation (Show whether DF, RT, GR, etc.) 4444.4' GR		12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Plugged well as follows:
Set CIBP at 3933' and cap w/35' cement.
Plug #1 3450' w/35 sx cement.
Cut 4-1/2" casing at 2584' and pulled 61 joints.
Plug #2 2634' w/35 sx cement w/2% CaCl. Tagged plug at 2218'.
Plug #3 2050' w/35 sx cement.
Plug #4 1710' w/35 sx cement. Tagged plug at 1640'.
Plug #5 1640' w/25 sx cement.
Plug #6 Surface plug w/10 sx cement.
Install dry hole marker.
Note: Mud between plugs.
Plugging completed 4-15-87.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Joyanta D. Doolittle</u>	TITLE <u>Production Supervisor</u>	DATE <u>4-20-87</u>
APPROVED BY <u>Jack Griffin</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JAN 04 1989</u>
CONDITIONS OF APPROVAL, IF ANY:		

HOBBY OFFICE

APR 21 1987

RECEIVED

100-100000

100-100000