

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Durwood XW
3. Address of Operator 105 S. Fourth, Artesia, N.M. 88210		9. Well No. 2
4. Location of Well UNIT LETTER <u>0</u> <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>18</u> TOWNSHIP <u>7S</u> RANGE <u>32E</u> NMPM.		10. Field and Pool, or WHdcat Tomahawk SA
15. Elevation (Show whether DF, RT, GR, etc.) 4444.4'GR		12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well is no longer commercial to produce. We propose to plug and abandon as follows:

Spot 25 sx cement plug from PBTD to 100' above perms. Top of San Andres 3398'. Cut & pull 4½" casing from about 3400', circulate hole with mud. Spot 35 sx cement plug across stub & tag (3450-3350'), Spot 35 sx cement plug at top of salt at 2050-1950', spot 35 sx cement plug across 8 5/8" shoe at 1710-1610', spot 10 sx cement plug at surface w/dry hole marker. Clean location and ready for inspection.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie L. Kautz TITLE Senior Engineer DATE 11-26-86

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY Paul Kautz TITLE Geologist DATE DEC 1 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
DEC 2 1986
O. P. B. CRUCE
HOSBYS CRUCE