

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY  
HOBBS NEW MEXICO 88240

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 36485

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P&A		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Yates Petroleum Corporation		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210		8. FARM OR LEASE NAME Folly ZO Federal	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330 FNL & 990 FEL, Sec. 24-T7S-R32E		9. WELL NO. 1	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Chaveroo SA	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4442.1' GR		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit A, Sec. 24-T7S-R32E	
		12. COUNTY OR PARISH Roosevelt	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to plug and abandon well as follows:

Set CIBP @ 4060' w/35' cement on top.

Cut 5 1/2" casing @ 3580' and lay down casing.

Set 100' cement plug @ 3630-3530' (50' in & out of stub).

Set 100' cement plug @ 2200-2100'.

Set 100' cement plug @ 1872-1772' (across 8-5/8" shoes).

Set 15 sx surface plug - 50' to surface.

Verbal approval for plugging given by Mr Armando Lopez, BLM, Roswell, NM, 11-9-84.  
Notify James Brasfield, BLM, Roswell before starting plugging of well.

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

(Orig. Sgd.) PETER W. CHESTER

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE Production Supervisor

DATE 11-12-84

TITLE

DATE

NOV 20 1984

\*See Instructions on Reverse Side