

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		<b>WELL API NO.</b> 30-041-20741
<b>1. Type of Well:</b> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		<b>5. Indicate Type of Lease</b> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
<b>2. Name of Operator</b> STATE OF NEW MEXICO		<b>6. State Oil &amp; Gas Lease No.</b>
<b>3. Address of Operator</b> 1625 N FRENCH DRIVE HOBBS NM 88240		<b>7. Lease Name or Unit Agreement Name:</b> PETERSON
<b>4. Well Location</b> Unit Letter <u>F</u> : <u>1980</u> feet from the <u>N</u> line and <u>1980</u> feet from the <u>W</u> line Section <u>17</u> Township <u>4S</u> Range <u>33E</u> NMPM County <u>ROSV</u>		<b>8. Well No.</b> 1
<b>10. Elevation (Show whether DR, RKB, RT, GR, etc.)</b> 4389		<b>9. Pool name or Wildcat</b> NORTH PETERSON

<b>11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data</b>			
<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

**12. Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ Telephone No. \_\_\_\_\_

(This space for State use)  
APPROVED BY Larry W. Wink **OC FIELD REPRESENTATIVE II/STAFF MANAGER** DATE AUG 06 2002  
Conditions of approval, if any \_\_\_\_\_

**STATE OF NEW MEXICO  
PAYMENT VOUCHER**



**DO NOT STAPLE BAR CODES**

EXPIRATION DATE	CONTRACT NUMBER
WARRANT NUMBER	

AGENCY CODE	521	DOCUMENT NUMBER	02-199-015050
DATE	05/22/02	BUDGET FY	02
		DOCUMENT TOTAL	11194.55
DOR 751498487			
DOOR NAME AND REMITTANCE ADDRESS			
AYO MARRS CASING PULLING INC			
) BOX 863			
4 N POPLAR			
RMIT TX79745			

AGENCY NAME ENERGY, MINERALS & NAT RES

REFERENCE DOCUMENT				FUND	AGCY	ORG/PRG	APPR UNIT	DIVISION	OBJECT	REVENUE SOURCE	REPT CATG	BALANCE SHEET ACCOUNT	DESCRIPTION	AMOUNT	P/F
CF	AGCY	DOC NUMBER	ACCT LN												
PC	521	02-199-003599		199	521	P586	360	0700	3522				PROF. SERVICES	11194.55	P
P E N D I N G															
TOTAL														11194.55	

02-199-003599 20 199 521 0750 301 0700 3522 PROF. SERVICES 11194.55 P

Sign Here: I certify that the above bill is correct and just and that payment therefore has not been received.

**FOR BOTH TRAVEL AND PURCHASE**

APPROVED BY:	DATE:	APPROVAL 1:	DATE:	APPROVAL 2:	DATE:
<i>Dr. Phil...</i>	<i>6/1/02</i>	<i>7...</i>	<i>6/1/02</i>		

AGENCY APPROVAL:

I certify that the goods or services were received or rendered, or the travel and related costs performed or incurred, in accordance with all contractual obligations and State (and if applicable Federal) legislation, rules and regulations.

AGENCY AUTHORIZED SIGNATURE: ☒ DATE:

\*\*\*\*\*  
INVOICE  
\*\*\*\*\*

Mayo Marrs Casing Pulling Inc.  
BOX 863  
Kermit, Texas 79745

\*\*\*\*\*  
INVOICE  
\*\*\*\*\*

Date 05-05-02  
INV. # 02-4635

OIL CONSERVATION DIVISION/HOBBS DISTRICT  
STATE OF NEW MEXICO  
1625 N. FRENCH DRIVE  
HOBBS, NEW MEXICO 88240

COMPANY: CASA PETROLEUM, INC.  
LEASE: PETERSON # 1  
CONTRACT # 02-521-07-156  
PLUGGING CONTRACT # 20-521-07-03599

CONTRACT PRICE TO P & A ..... \$ 15,460.00

WORK PERFORMED BEYOND CONTRACT:

PUMP TRUCK TO RESET PLUG ..... \$ 150.00


1 HR RIG TIME @ \$ 160.00/HR TO RESET PLUG ..... \$ 160.00

CREDIT:

2773' OF 5 1/2" CASING @ \$ 1.65/FT ..... - 4,575.45

Total \$ 11,194.55

*OK to Pay -  
C. Williams*



MAYO MARRS CASING PULLING INC.  
BOX 863  
KERMIT, TEXAS 79745


NEW MEXICO OCD  
BID ID # 00-521-07-03599

OPERATOR: CASA PETROLEUM, INC.  
Lease: PETERSON # 1  
Project: P & A – CEMENTING REPORT

---

4-23-2002 – SET CIBP @ 3875' – DUMP 35' CEMENT ON TOP – 3840'  
4-25-2002 – SPOT 40 SXS @ 2823'-2708' TAGGED  
PULLED 2773' OF 5 ½" CASING  
4-25-2002 - SPOT 40 SXS @ 1985'-1985' TAGGED  
4-25-2002 – SPOT 40 SXS @ 1985'-1860' TAGGED  
4-26-2002 – SPOT 30 SXS @ 350'-152' TAGGED  
4-23-2002 - SPOT 20 SXS @ 60' TO SURFACE

INSTALL DRY HOLE MARKER  
CIRCULATE 10# MUD LADEN FLUID



MAYO MARRS CASING PULLING INC.  
BOX 863 KERMIT, TEXAS 79745

NEW MEXICO OCD

ATTN: CHRIS WILLIAMS/GARY WINK

Lease: PETERSON # 1

OPERATOR: POE PROPERTIES

Project: P & A – BID I.D. # 20-521-07-03599

-----  
4-23-02

MIRU – NDWH – NUBOP – RIH WITH GAUGE RING TO 4240' – POOH – RIH &  
SET CIBP @ 3875' – DUMP 35' CEMENT ON TOP –

4-24-02

RIH WITH TUBING & CIR. 10# MUD – POOH – WELD ON PULL NIPPLE – CUT  
CASING @ 2773' – LAY – DOWN 25 JOINTS – CLOSE IN WELL

4-25-02

POOH WITH CASING – RIH & SPOT 40 SXS @ 2823' – POOH – WOC – RIH &  
TAG @ 2708' – POOH & SPOT 40 SXS @ 1985' – POOH – WOC – RIH – NO TAG –  
SPOT 40 SXS @ 1985' – POOH – WOC – CLOSE IN WELL

4-26-02

RIH & TAG @ 1860' – POOH – SPOT 30 SXS @ 350'-152' - POOH & SPOT 20 SXS  
@ 60' TO SURFACE - LEVEL PIT & CELLAR – RID DOWN – MOVE OUT – CUT  
OFF WELLHEAD – INSTALL DRY HOLE MARKER – MOVE OUT

