

ROOSEVELT
TEXAS CRUDE INC

Wildcat
1 Landers "30"

NM
Page #2

4-15-85

Continued

DST (Fusselman) 7867-7917, op 2 hrs, rec 60 FT
MUD (Sample chamber rec 1700 CC MUD), 30 min
IFP 32-32, 1 hr ISIP 1049, 1 hr 30 min FFP
3243, 2 hr FSIP 1282, HP 4263-4263, BHT 128
deg

4-22-85

TD 8385; Rng Logs

DST (Fusselman) 8060-8143, op 2 hrs, rec 465 FT
MUD + 2035 FT SULW (Sample chamber rec 2400
CC SULW), 30 min IFP 128-490, 1 hr ISIP 2860,
1 hr 30 min FFP 554-1171, 2 hr FSIP 2860, HP
4347-4376

4-25-85

No Cores

TD 8385; D&A

5-3-25 NM

5-13-85

TD 8385; Dry & Abandoned

*LOG TOPS: Yates 2218, Glorieta 4572, Tubb
5868, Abo 6605, Pennsylvanian 7755, Silurian
7940, Fusselman 8140

*LOGS RUN: BHCS, CNDL, MSFL, DIPM, DLL
Rig Released 4-23-85

5-18-85

*Denotes changes & additions

6-29-85

COMPLETION ISSUED

11-2-85

RE-ISSUED COMPLETION TO CORRECT DST INTERVAL
& TO MOVE DST TO PREVIOUS DAYS ENTRY
RE-ISSUED COMPLETION

5-3-25 NM

IC 30-041-70067-84

WELL CLASS: INIT WF FIN WF LSE. CODE			
FORMATION	DATUM	FORMATION	DATUM
TD	8385 (FSLM)	PBD	

CSC
 13 3/8-391-420 sx
 8 5/8-3350-1200 sx

DRY & ABANDONED

CONTR Norton Drlg #8 OPRSELEV 4278 GR, 4292 KB SUBS 13

F.R. 12-31-84
 PD 8500 RT (Fusselman)
 Drlg 3481
 3-26-85 Drlg 6205 dolo, anhy & sh
 4-2-85 Att DST (San Andres) 4238-4360, misrun, could
 not get tool to bottom
 DST (San Andres) 4238-4360, op 30 mins, DP rec
 (NR) (Sample chamber rec 2350 CC FLUP), 30 min
 IFP *(NR), 1 hr ISIP 1488, tool would not open
 for FF, HP 2050-2132, stuck DP in hole
 DST(San Andres) 4255-4360, op 2 hrs 30 mins,
 rec 630 FT MUD (Sample chamber rec 2500 CC MUD).
 30 min IFP 64-85, 1 hr ISIP 1467, 2 hr FFP 106-
 256, 4 hr FSIP 1456, HP 2059-2059
 Drlg 7630 lm, dolo & sh
 4-8-85 Drlg 7952
 4-15-85 Att DST (Fusselman) 7885-7917, misrun, pkr failed
 5-3-25 NM