

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ For ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Bravo "ABO"
3. Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER N 550 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 33 TOWNSHIP 3S RANGE 30E NMPM.	10. Field and Pool, or Wildcat Wildcat Granite
15. Elevation (Show whether DF, RT, GR, etc.) 4446' GR	11. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal permission obtained from Jerry Sexton, OCD, Hobbs to plug and abandon well 4-10-85.

Plugged well as follows: 4-11-85.

Plug #1: 8530-8430'	Spotted 30 sx Class "C".	PD 8:35 AM. WOC 40 mins.
Plug #2: 7875-7775'	Spotted 40 sx Class "C".	PD 9:35 AM. WOC 1 hr and 55 mins.
Plug #3: 7300-7200'	Spotted 45 sx Class "C".	PD 12:00 noon. WOC 1 hr.
Plug #4: 5965-5865'	Spotted 50 sx Class "C".	PD 1:15 PM. WOC 1 hr and 15 mins.
Plug #5: 3800-3700'	Spotted 30 sx Class "C".	PD 2:45 PM. WOC 45 mins.
Plug #6: 2700-2600'	Spotted 30 sx Class "C".	PD 3:45 PM. WOC. Tagged plug at 2620'.
Plug #7: 1000-900'	Spotted 35 sx Class "C".	PD 5:50 PM. WOC 50 mins.
Plug #8: Surface	Spotted 60 sx Class "C".	PD 6:45 PM.

Installed dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Juanita Goodlett</u>	TITLE <u>Production Supervisor</u>	DATE <u>4-12-85</u>
APPROVED BY <u>Jack Griffin</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>SEP 17 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		