

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
AMOCO PRODUCTION COMPANY

Address of Operator
P.O. BOX 68 HOBBS, NEW MEXICO 89240

Location of Well
UNIT LETTER **C** **330** FEET FROM THE **North** LINE AND **1650** FEET FROM
THE **West** LINE, SECTION **19** TOWNSHIP **5-8** RANGE **33-E** N.M.P.M.

5a. Indicate type of Lease
State ☐ Free ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name
WILBANKS

9. Well No.
1

10. Field and Pool, or Wildcat
Peterson - Fusselman

11. Elevation (Show whether DF, RT, GK, etc.)
4419.1 GR

12. County
Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

OR ALTER CASING ☐ OTHER ☒ **Perforate Add'l pay and Stimulate**

SUBSEQUENT REPORT OF:

OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to: MISU and POH w/ production equipment. Tag PBTD of 7832'. If fill is encountered, CO to PBTD and POH. RIH w/ 3 1/8" csg gun and perf the Fusselman interval 7800'-13' w/ 4 DPJSPF w/ 90° phasing and POH. RIH w/ PPI phr for 5 1/2" csg, collar locator, retrievable fluid plug, unloader and 2 7/8" tbg. Set phr at 7780'. Open bypass and circ 50 bbl water to flush out tbg. Rel phr and lower to 7823'. RIH w/ RFC valve preset to appx 4600 psi. Treat 7800'-23' w/ 50 gal / ft, treating one foot at a time, w/ 15% HCL w/ add. Pull phr up to ± 7700' and set. Retrieve RFC valve and fluid plug. Open bypass while pmp acid to phr. Close bypass and pump 1200 gal 15% NEFE HCL acid w/ add. Flush w/ 55 bbl water. Swab
045 NMCD-H, 1-JRB, 1-FJN, 1-NLG

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

by *Chick L. Gater* TITLE Administrative Analyst DATE 17 June 1985

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

DATE JUN 19 1985

to recover load. Rel pkr, tag PBD, and POH. R1H w/ 3 1/2" x 20' long mother hubbard, SN, 5 jts 2 7/8" tbg, tbg anchor, and 2 7/8" tbg. Set anchor at 7640', SN at 7794', and mother hubbard at 7816'. Run rods and pump. RD and MOSD.