State of New Mexico Form C-103 Submit 3 Copies Energy, Minerals and Natural Resources Department to Appropriate ... District Office Revised 1-1-89 OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-041-20794 DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 LG 1296 SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: OIL WELL El Paso State X WELL 2. Name of Operator 8. Well No. Bledsoe Petro Corporation 9. Pool name or Wildcat Address of Operator South Peterson Penn/Assoc. Peniel, Suite 500, Bethany OK 73008 3908 N. 510 : 1980 Feet From The \_\_ East Line and Feet From The Line 68 Range 34E **NMPM** Roosevelt County Section Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDONMENT CHANGE PLANS COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CASING TEST AND CEMENT JOB PULL OR ALTER CASING OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. See Attached Plugging Report

TYPE OR PRINT NAME Chris Ball

THE DATE

TYPE OR PRINT NAME Chris Ball

THE DATE

THE

Agent

information above is frue and complete to the best of my knowledge and belief.

d. In

I hereby certify that the

CONDITIONS OF APPROVAL, IF ANY:

(6

111/03/92

RECEIVED
NUV 0 6 1992
OCD HOBBS OFFICE

## Plugging Report

## Bledsoe Petroluem Incorporated El Paso State #4, Roosevelt County, N.M.

PLugged By: Ball Oilfield Service - Box 818 - Eastland, Texas 76448

9/29/92 Rig to location. Rig up. Unseat pump start out of hole with rods. SDFN

9/30/92 Finish laying down rods. Lay down 238 joints 2 3/8 tubing. Set CIBP at 7600'. Dump 2 sx cement on top of plug. Load hole . Run bond log. SDFN

10/01/92 Break down casing head. Weld on pull nipple. Work Casing. Cut Casing at 4300'. SDFN

10/02/92 Lay down 4300' 4 1/2 casing. Shut well in. SDFN

10/05/92 Run tubing to 4350. Mixed 200 bbl mud. Well did not circulate. SDFN

10/06/92 Mixed 130 bbls mud. Well is circulating. Pumped 45 sx Cl. A cement at 4350'. Pull tubing to 3400. Wait 4 hrs. Run tubing to 4205' - tag plug. Pull tubing to 3400'. Pump 45 sx Cl A cement. Pull tubing to 2000' and pump 60 sx Cl A cement. Pull tubing to 800'. SDFN

10/07/92 Shut down due to high wind.

10/08/92 Run tubing to 1790' to tag plug. Pull tubing to 30'. Pump 10 sx Cl A cement. Lay down tubing. Cut well head and casing off 4 feet below GL. Weld cap on surface. Install abandoned well marker. Cover cellar and pit. Clean up location for abandonment.