

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
IG 1296	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. Name of Operator		7. Unit Agreement Name	
BHP Petroleum (Americas) Inc.			
2. Address of Operator		8. Farm or Lease Name	
P. O. Box 2437 Midland, TX 79702		El Paso State	
3. Location of Well		9. Well No.	
UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>510</u> FEET FROM		4	
THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>6 S</u> RANGE <u>34 E</u> NMPM.		10. Field and Pool, or Wildcat Assoc.	
		South Peterson Penn/	
11. Elevation (Show whether DF, RT, GR, etc.)		12. County	
4371.4 GL		Roosevelt	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) See attached "Completion Data Sheet" for well schematic and history of operations.
- 2) Operations to plug this well will commence upon approval by partners. We estimate these proceedings will begin in the last half of March 1986.
- 3) We propose: To plug and abandon the well as follows:
 - a. Set a CIBP @ 7650' w/35 feet of cement on top.
 - b. Load hole w/10# salt gel.
 - c. Run a free point and shoot off 4½" casing at free point, possibly @ 5500'. Pull casing.
 - d. Spot 100 feet of cement across casing stub @ 5500', leaving 1/2 in and 1/2 out.
 - e. Pull up hole and let cement set for 4 hours. Tag top of cement.
 - f. Spot 100 feet of cement at 3150' inside 7 7/8" hole.
 - g. Spot 100 feet of cement across bottom of 8 5/8" casing at 1961' leaving 1/2 in and 1/2 out. Pull up and let cement set for 4 hrs. Tag top of cement.
 - h. Spot 100 feet of cement inside 8 5/8" casing at 1800 feet.
 - i. Spot 10 sx of cement at surface.
 - j. Weld on NMOCC approved P&A marker.

THIS DOCUMENT IS NOTIFIED 24
HOURS BEFORE THE EXPIRATION OF
THE PERIOD FOR FILING A
PETITION FOR REVIEW OF THIS
DECISION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Michael L. Jones</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>2-17-86</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE <u>FEB 18 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
FEB 17 1986
HOBBS OFFICE