

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY		7. Unit Agreement Name	
2. Name of Operator BWAB INCORPORATED		8. Farm or Lease Name RADCLIFF 10-44	
3. Address of Operator 1801 California Street, Suite 1000, Denver, CO 80202		9. Well No. #1	
4. Location of Well UNIT LETTER M 330' FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 10 TOWNSHIP 6S RANGE 35E NMPM.		10. Field and Pool, or Wildcat Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) 4,220' GR		12. County Roosevelt	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Sitton Drilling, 916 Main, Suite 503, Lubbock, Texas 79401, received verbal approval from Mr. Jerry Sexton of the Hobbs District Office on 04/01/86 to plug and abandon the Radcliff 10-44 #1 in the following manner:

Plug #1 7,863' 100 sx  
Plug #2 7,373' 100 sx  
Plug #3 7,031' 100 sx  
Plug #4 4,500' 100 sx  
Plug #5 4,100' 100 sx  
Plug #6 3,345' 100 sx  
Plug #7 1,300' 100 sx  
Plug #8 Set a 10 sx plug on top of 8-5/8" csg set 18" below GR.  
Set a dry hole marker.

Prepare to restore the location and will notify the State of New Mexico when the location is ready for inspection.

03-12-86 Spudded at 3:00 p.m.  
Ran 9 jts of 13-3/8", 54.5#, J-55, ST&C csg & set @ 352'. Cem w/ 350 sx CI "C" cen  
03-19-86 Ran 81 jts of 8-5/8", 32# & 24# csg set @ 3,395', cemented with 940 sx cement.  
04-01-86 Logging. Ran DLL/GR, LDT, CNL/GR, Caliper.  
04-01-96 Prepared to plug and abandon well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John R. Keller TITLE Production Superintendent DATE 04/03/86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE

DATE

APR 8 - 1986

CONDITIONS OF APPROVAL, IF ANY: