

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20809
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Stoltenberg
8. Well No. 1
9. Pool name or Wildcat Tule; San Andres (Gas)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4394 GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator MARSHALL PIPE & SUPPLY COMPANY
3. Address of Operator 12700 Preston Road - Suite 165 Dallas, Texas 75230
4. Well Location Unit Letter F : 1650 Feet From The North Line and 2310 Feet From The West Line Section 26 Township 2S Range 29E NMPM Roosevelt County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4394 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing Set in Well: 4-1/2" 11.60# set at 3117'

Set a plug within 100' from perforations at 2920' with wireline ser.
Fill hole with packer fluid and water, pressure up to 500# and
hold 30 minutes.
Submit a chart showing this pressure test upon completion.

This information was obtained from Gary Wink by telephone on
2-25-97. If additional information is desired, please advise.
We will have our field man, Shane Ferguston, telephone Mr. Wink
and learn full procedure, calling 505-393-6161.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Agent

DATE

4-2-97

972-239-7284

TYPE OR PRINT NAME

Virginia Lee Johnson

TELEPHONE NO.

(This space for State Use)

ORIGINAL FILED BY JERRY SEXTON

DISTRICT I SUPERVISOR

APR 10 1997

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: