

WORK SHEET FOR CALCULATION OF WELLHEAD PRESSURE (P_c or P_w)

FORM C-122F

FROM KNOWN BOTTOM HOLE PRESSURE (P_f or P_s)

COMPANY MARSHALL PIPE& SUPPLY LEASE :STOL BERG WELL NO. : 1 DATE :10 2 92
 UNIT F SECTION : 26 TOWNSHIP : 2 RANGE : 29
 L 2925 H : 2925 L/H : 1 G/GMIX : 0.6990
 CO2 : 2.99 N2 : 11.26 H2S : 0.41
 GH : 2044.6 PCR : 658 TCR : 355

LINE		1	2	3	4	5	6	7	8
1	TW(W.H. R)	534	534	534	534	534	534	534	534
2	Ts(B.H. R)	563.3	563.3	563.3	563.3	563.3	563.3	563.3	563.3
3	T=(Tw+Ts/2)	548.6	548.6	548.6	548.6	548.6	548.6	548.6	548.6
4	Z (EST.)	0.898	0.841	ERR	ERR	ERR	ERR	ERR	ERR
5	TZ	493	461	ERR	ERR	ERR	ERR	ERR	ERR
6	GH/TZ	4.150	4.431	ERR	ERR	ERR	ERR	ERR	ERR
7	eS(TABLE XIV)	1.168	1.181	ERR	ERR	ERR	ERR	ERR	ERR
8	Pf or Ps	1135.2	1135.2	0	0	0	0	0	0
9	Pf2 or Ps2	1288.7	1288.7	0.0	0.0	0.0	0.0	0.0	0.0
10	Pc2=Pf/eS or Pw2=Ps2/eS	1103.0	1091.4	ERR	ERR	ERR	ERR	ERR	ERR
11	Pc or Pw	1050	1045	ERR	ERR	ERR	ERR	ERR	ERR
12	P=(Pw+Ps/2)or(Pc+Pf/2)	1093	1090	ERR	ERR	ERR	ERR	ERR	ERR
13	Pr=(P/PCR)	1.66	1.66	ERR	ERR	ERR	ERR	ERR	ERR
14	Tr(T/TCR)	1.55	1.55	1.55	1.55	1.55	1.55	1.55	1.55
15	Z (TABLE XI)	0.841	0.841	ERR	ERR	ERR	ERR	ERR	ERR

P_c ~~1~~ : 1044.7 PW 2 : ERR PW 3 : ERR PW 4 : ERR

1049.2

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20809
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Stoltenberg
8. Well No. 1
9. Pool name or Wildcat wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	
2. Name of Operator MARSHALL PIPE & SUPPLY COMPANY	
3. Address of Operator 13423 Forestway Dr., Dallas, Texas 75240	
4. Well Location Unit Letter F : 1650 Feet From The North Line and 2310 Feet From The West Line Section 26 Township 2S Range 29E NMPM Roosevelt County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4394 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	Perforated Casing: ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

September 24th, 1992: Perforated 3038' to 3048', 21 holes, acidized with 1500 gal of 10% MCA. Swabbed well - turned to water. Set permanent plug at 3015', 3 sacks of cement - filled up 35'. Top of Plug at 2980'.

September 26th, 1992: Perforated 2920 to 2930'. acidized and tested. Well cleaned up and flowing natural gas.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. W. Marshall TITLE Operator DATE 10-1-92
TYPE OR PRINT NAME J. W. Marshall TELEPHONE NO. 214-239-7284

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR TITLE DATE OCT 18 1992
CONDITIONS OF APPROVAL, IF ANY: RECEIVED