

OIL CONSERVATION DIVISION

P. O. BOX 2085
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REFRACK OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
The Long Trusts

Address of Operator
P.O. Box 1336 Kilgore, Texas 75662

Location of Well
UNIT 1211A 0 900 FEET FROM THE North LINE AND 1650 FEET FROM THE East LINE, SECTION 3 TOWNSHIP 6S RANGE 33E NMPM.

5c. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name
Lambirth B

9. Well No.
3

10. Field and Pool, or Wildcat
Wildcat

11. Elevation (Show whether DF, RT, GR, etc.)
4396' G.R.

12. County
Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
REFRACK OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

As per OCD plugging procedure:

5/10/87 Ru Western and set plugs as follows:

plug 1	8160(T.D.)	40sx	C1 "C"
plug 2	7900	40sx	C1 "C"
plug 3	5900	70sx	C1 "C"
plug 4	4050	70sx	C1 "C"
plug 5	2050	50sx	C1 "C"

5/11/87 Set 10sx plug at surface. Jet pits and release rig.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signature: *William H. "Dub" Storch* Title: Operations Engineer Date: 10/15/87
Signature: *Jack Griffin* Title: OIL & GAS INSPECTOR Date: JAN 13 1989