HARD CHARRING ONE TONGE	i Menu			
HO, OF ESPICE SCLEIVES		DNSERVATION	DIVISION	
DISTRIBUTION P. O. BOX 2088				Form C-103 Revised 1C-1-78
SANTA FE	SANTA FE, NEW MEXICO 87501			
FILE				Sa. Indicate Type of Lease
U.S.G.S.				State Fee X
OPERATOR	\exists	•		5, State Otl & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS				
USE "APPLICATION FOR PERMIT =" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lait Agreement Name
OIL X WELL	OTHER•			
ume of Operator				8. Farm or Lease Name
The Long Trusts				Lambirth B
Address of Operator				9. Well No.
	1336, Kilgore, T	X /5662		10. Field and Pool, or Wildcat
ocation of Well	900	North	1650	
	CTION3 YOW			
15. Elevation (Show whether DF, RT, GR, etc.)				12. County
		4396 G.L.		Roosevelt (
Chec	k Appropriate Box T	o Indicate Nature of	Notice Report of (Other Data
	INTENTION TO:	Indicate Hatare of	•	NT REPORT OF:
FURM REMEDIAL WORK	PLUG AN	D ABANDON X REMEDIAL	WORK	ALTERING CASING
APORARILY ABAHOON		* *	DRILLING OPHS.	PLUG AND ABANDONMEN'
L OR ALTER CABING	CHANGE		ST AND CEMENT JQB	
OTHER		OTHER		LJ
Completed	Operations (Clearly state)	Il pertinent details, and air	e pertinent dates, includi	ng estimated date of starting any proposed
work) SEE RULE 1103.				
	Cautz with the Oil plugging procedur		vision of intent	tion to P/A
Rig up Wester	rn Company:			
1 stage	8160 (TD)	40 sacks	Class C	
2 stage	7900	40 sacks	Class C	· · · · · · · · · · · · · · · · ·
3 stage	5900	70 sacks	Class C	
4 stage	4050	70 sacks	Class C	

ORIGINAL SIGNED BY JERRY SEXTON

THE Petroleum Engineer

ONLY 2 9 1987

50 sacks

10 sacks

Class C

Class C

5 stage

6 stage

2072

Surface plug

