Form C-105 STATE OF NEW MIEXICO Revised 10-1-78 ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION NO. OF COPIES RECEIVED 5a. Indicate Type of Lease P. O. BOX 2088 DISTRIBUTION State Fee X SANTA FF SANTA FE, NEW MEXICO 87501 5. State Oil & Gas Lease No. FILE U.S.G.S. WELL COMPLETION OR RECOMPLETION REPORT AND LOG LAND OFFICE OPERATOR la. TYPE OF WELL b. TYPE OF COMPLETION 8. Farm or Lease Name GARDNER "17" 2. Name of Operator 9. Well No. MAXUS EXPLORATION COMPANY 3. Address of Operator F.O. Box 10397 10. Field and Pool, or Wildcat Midland, TX 79702 WILDCAT 4. Location of Well 467 SOUTH 1980 RGE. 36-E THE WEST LINE OF SEC. 17 6-S ROOSEVELT TWP. NMPM A 16. Date T.D. Reached 17. Date Compl. (Ready to Prod.) 15. Date Spudded 18. Elevations (DF, RKB, RT, GR, etc.) 19. Elev. Cashinghead 05-30-88 06 - 23 - 8806-26-88 4143' 20. Total Depth 21. Plug Back T.D. 22. If Multiple Compl., How 23. Intervals , Rotary Tools
Drilled By Cable Tools 8161' Χ 24. Producing Interval(s), of this completion - Top, Bottom, Name 25. Was Directional Survey No 26. Type Electric and Other Logs Run 27. Was Well Cored DIL/GR, CNL/FDC, LLS/GR, DIPMETER 28. CASING RECORD (Report all strings set in well) CASING SIZE WEIGHT LB./FT. DEPTH SET HOLE SIZE CEMENTING RECORD AMOUNT PULLED 13-3/8" 48# 399' 17 1/2" 420 sx Premium Plus 8-5/8" 3274' 24-28# 1/4" 400 sx Premium Plus HLC 1250' Tail in w/200 sx "H" 29. LINER RECORD 30. TUBING RECORD SIZE TOP BOTTOM SACKS CEMENT SCREEN SIZE DEPTH SET PACKER SET 31. Perforation Record (Interval, size and number) 32. ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC. DEPTH INTERVAL AMOUNT AND KIND MATERIAL USED 33. PRODUCTION Date First Production Production Method (Flowing, gas lift, pumping - Size and type pump) Well Status (Prod. or Shut-in) Date of Test Hours Tested Choke Size Oil - Bbl. Gas - MCF Water - Bbl. Gas - Oil Ratio Test Period Flow Tubing Press. Casing Pressure Calculated 24-Hour Rate Oil - Bbl. Gas - MCF Water - Bbl. Oil Gravity - API (Corr.) 34. Disposition of Gas (Sold, used for fuel, vented, etc.) Test Witnessed By 35. List of Attachments Letter requesting log confidentiality / Inclination Survey Record i. I hereby certify that the information shown on both sides of this form is true and complete to the best of my knowledge and belief. TITLE Sr. Drilling Engineer

07 - 12 - 88

DATE

INSTRUCTIONS

This form is to be filed with the appropriate District Office of the Division not later than 20 days after the completion of any newly-drilled or deepened well. It shall be accompanied by one copy of all electrical and radio-activity logs run on the well and a summary of all special tests conducted, including drill stem tests. All depths reported shall be measured depths. In the case of directionally drilled wells, true vertical depths shall also be reported. For multiple completions, Items 30 through 34 shall be reported for each zone. The form is to be tiled in quintuplicate except on state land, where six copies are required. See Rule 1105.

INDICATE FORMATION TOPS IN CONFORMANCE WITH GEOGRAPHICAL SECTION OF STATE

Southeastern New Mexico

								Northw			
Anhy			т.	Canyon	T.	Ojo Ala	amo		Т.	. Penn. "B"	
Salt_			T.	Strawn	T.	Kirtlan	nd-Frui	tland	т	Penn. "C"	
Salt_		· · · · · · · · · · · · · · · · · · ·	T.	Atoka	T.	Picture	ed Clif	fs	Т.	Penn, "D"	
Yates	s		T.	Miss	T.	Cliff H	louse_		Т.	Leadville	
7 Riv	ers		T.	Devonian	Т.	Menefe	e		Т.	Madison	
Queer	n		Т.	Silurian	Т.	Point L	ookou	t	T.	Elbert	
Grayb	ourg		Т.	Montoya	T.	Mancos	·		T.	McCracken _	
San A	Indres _		T.	Simpson	T.	Gallup			Т.	Ignacio Otze	e
Glorie	eta		Т.	McKee	Bas	e Green	nhorn _		т.	Granite	
Paddo	ock		Т.	Ellenburger	Т.	Dakota			T.		
Bline	bry		Т.	Gr. Wash	Т.	Morriso	n		Т.		
Tubb.			Т.	Granite	T.	Todilto	·		Т.		
Drink	ard		T.	Delaware Sand	T.	Entrada	a		Т.		
Abo _			T.	Bone Springs	Т.	Wingate	·		Т.		
Wolfca	amp		Т.		T.	Chinle .			т.		
Penn.			<u> —</u> Т.		T.	Permian	n		Т.		
Cisco	(Bough	C)	T.		т.	Penn '	'A''		т.		
					GAS SA						
1, from	ì	*************************		to						to	
2, fromto											
3 fmm	,			to							********
ide dat	a on rai	***************************************		d elevation to which wate	·*···	ole.		feet.	***************************************		
ude dat 1, from 2, from	a on rai	************************		d elevation to which wate	er rose in he	ole,		feet.	•••••	*************************	***************
ude dat 1, from 2, from 3, from	a on rai			toto	er rose in he	ole,		feet.	************	······································	
ude dat 1, from 2, from 3, from	a on rai			toto	er rose in he	ole,		feet.	************	······································	
ude dat 1, from 2, from 3, from	a on rai			d elevation to which wate	er rose in he	ole.		feet.		······································	
ude dat 1, from 2, from 3, from	a on rai			toto	Attach addit	ole.		feet.		······································	
ide dat 1, from 2, from 3, from	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
de dat., from., from., from.	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
de dat., from., from., from.	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
de dat. , from. , from. , from.	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
de dat., from., from., from.	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
de dat., from., from., from.	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
de dat. , from. , from. , from.	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
from.	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
ide dat. 1, from. 2, from. 3, from.	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
ide dat. 1, from. 2, from. 3, from.	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
ude dat 1, from 2, from 3, from 4, from	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
ude dat 1, from 2, from 3, from 4, from	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			
ide dat 1, from 2, from 3, from	a on rai	Thickness		toto	Attach addit	tional sh	heets i	feet. feet. freet. f necessary			