

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20844
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name McAlister
2. Name of Operator Tamarack Petroleum Co., Inc.	8. Well No. #1
3. Address of Operator 500 W. Texas, Suite 1485, Midland, TX 79701	9. Pool name or Wildcat Wildcat
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>south</u> Line and <u>1980</u> Feet From The <u>west</u> Line Section <u>28</u> Township <u>G 5 6 8</u> Range <u>33-E</u> NMPM <u>Roosevelt</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4414.5' GB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Start plugging operating 6/04/89
2. Circulate hole with 9.9 mud.
3. Spot cement plug through open-ended drill pipe at the following:
8500' with 45 sks Class "H" (100')
6627' with 45 sks Class "H" (100')
4535' with 45 sks Class "H" (100')
2166' with 50 sks Class "H" (100')
1100' with 50 sks Class "H" (100')
10 sks surface plug
4. Set surface marker.
5. Clean Location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Harold Green TITLE Production Superintendent DATE June 5, 1989
TYPE OR PRINT NAME Harold Green TELEPHONE NO. 915-683-5474

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE OCT 23 1989
CONDITIONS OF APPROVAL, IF ANY: