

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20850
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Ladson
8. Well No. 1
9. Pool name or Wildcat Wildcat

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Hanson Operating Company, Inc.	
3. Address of Operator P. O. Box 1515, Roswell, New Mexico 88202-1515	
4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>24</u> Township <u>1-S</u> Range <u>31-E</u> NMPM <u>Roosevelt</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4236' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Received verbal approval from Paul Kautz of NMOCDD on 05/01/90 to plug and abandon.

05/02/90 - Plugged and abandoned well in the following manner:

35 sx 100' cemented plug at TD 7075'.  
50 sx 100' cemented plug at 5399' - Abo.  
50 sx 100' cemented plug at 3312' - Glorieta.  
60 sx 50' in & 50' out at 8-5/8" csg shoe 2495'.  
Tagged plug at 2434'.  
30 sx 100' cemented plug at 13-3/8" csg shoe 350'.  
10 sx cemented plug at surface.  
All plugs were Class "H" cement.  
Rig released @ 11:00 p.m., 05/02/90.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Brenda R. Godfrey TITLE Production Analyst DATE 05/08/90

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY Jack Bruffin TITLE OIL & GAS INSPECTOR DATE JAN 19 1992

CONDITIONS OF APPROVAL, IF ANY: