

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20869
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Parks Unit
8. Well No. 1
9. Pool name or Wildcat Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER dry hole	
2. Name of Operator Murphy H. Baxter	
3. Address of Operator P O Box 2040, Midland, Texas 79702	
4. Well Location Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line Section 21 Township 6 Range 36 NMPM Roosevelt County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4109.3 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Set 5 1/2 CIBP @ 8150, cap w/35' cement
- (2) Load hole w/mud
- (3) Cut & pull 5' casing from 7279'
- (4) Spot 30 saCks cement @ 5 1/2 stub 7239', WOC Tag plug @ 7225'
- (5) Spot 30 sacks cement @ 4790'
- (6) Spot 30 sacks cement @ 3553, 8 5/8 shoe, WOC, tag plug @ 3515, plug was low.
- (7) Spot 30 sacks cement @ 3515'
- (8) Cut & pull 8 5/8 casing @ 1642'
- (9) Spot 65 sacks cement @ 1692', 8 5/8 stub, WOC, Tag plug @ 1589'
- (10) Spot 75 sacks cement @ 447', 13 3/8 shoe, WOC, tag plug @ 407', plug was low
- (11) Spot 50 sacks cement @ 407'
- (12) Spot 20 sacks cement @ Surf, set P&A marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jim Hearn TITLE MGR. DATE 6-3-93

TYPE OR PRINT NAME Jim HEARN TELEPHONE NO. 6835321

(This space for State Use)

APPROVED BY Jack Griffin DATE 6/11/93

CONDITIONS OF APPROVAL, IF ANY: