Submit 3 Copies to Appropriate District Office

State of New Mexico E....gy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

P.O. Box 1980, Hobbs, NM 88240		OIL CONSERVATION DIVISION			ON $\overline{\mathbf{w}}$	LL API NO.		——	
DISTRICT II		P.O. Box 2088 Santa Fe, New Mexico 87504-2088				30-041-20872			
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III					5.	5. Indicate Type of Lease			
1000 Rio Brazos Rd.,		6	State Oil & C	STATE Sas Lease No.	<u> </u>	FEE			
			·			State Oil & (J44 LEASE NO.	VA-6	10
(DO NOT USE THE	LLS				//////				
	NOR PLUG BACK ERMIT"	TO A 7.	Lease Name	or Unit Agreeme	nt Name				
1. Type of Well: OIL WELL	GAS X	•	OTHER			Cougar	113611 6464		
2. Name of Operator	8.	Cougar "36" State 8. Well No.							
Santa Fe Energy Operating Partners, L.P. 3. Address of Operator							<u> </u>		
550 W. Tex	79701		9. Pool name or Wildcat Wildcat (Montoya)						
A METI TOCHROR				, , , , , , , , , , , , , , , , , , , ,			(Honeoya)		
Unit Letter _	H : 1980	Feet From The _	North	Line and _	660	Feet Fro	m TheE	ast	Line
Section	36	Township I	S D.	inge 31E	.	_	Pagas-1		
		10. Elevan	ion (Show whether	DF, RKB, RT, GR, e	NMPN	4	Roosevel	t <i>777777</i>	County
			4236' GR						
11.	Check A	ppropriate Box	to Indicate	Nature of Noti	ce, Report	t, or Othe	r Data		
						SUENT	REPORT)F:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK							ALTERING C	ASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING						. \Box			
PIN LODALTED CASING						_	PLUG AND A	BANDON	MENT
OTHER:	CASING TEST A	IND CEMENT	JOB LX						
				OTHER:					🗆
12. Describe Proposed o work) SEE RULE 1	r Completed Operation 103.	05 (Clearly state all p	vertinent details, an	d give pertinent dates	s, including est	imated date o	f starting any pro	oposed	
11/22/93:	, _00 022	'. RU casin O'. Cemente Cl "C" + 2% WOC. Teste	CaClo. Ci	SX Pacesett	er Lite	+ 2% Ca			
11/23/93:	Cut casing off and weld on head. NU BOP's.								
11/24/93:	PU BHA and trip in hole. Tag cement at 2310'. Resume drilling.								
11/28/93:	1/28/93: Depth 5570'. TOH. Cut drlg line. RU. Test pipe rams, blind rams, manifold to 3000 psi, held ok. Test Hydril to 1000 psi, held ok. TIH w/ bit #5. Install rotating head. Resume drilling.								
I hereby certify that the info	amation above is true an	Fomplete to the best of	my knowledge and h	elief.					
SIGNATURE	MINCE	<i>!</i> // //	1/ -	Sr. Produc	ction Cl	erk	No	₃₇ 20	1002
TYPE OR PRINT NAME	Terry McCul	/	1110			LIK		v. 29, 915	/
(This space for State Use)							TELEPHONE N	. 00/	-3551
from shore tot same cas)		NED BY JERRY					.		
APPROVED BY	DISTRI	ct i superviso	<u>R</u> TITLE				_ DEC (1 199	3